

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Mark BRETNALL BPB No. 0047	380	2-10 Lake Albert Road, East Wagga Wagga	Mr Brentnall failed to ensure development consent conditions ('pre conditions') were satisfied before he issued an occupation certificate.	Mr Brentnall was reprimanded and ordered to pay a fine of \$5,000.	22/11/2014