

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Glenn <b>LEVICK</b>  BPB No. 0227	301	52 Lakeview Parade, Pelican	Mr Levick failed to enforce a condition of consent requiring verification of the floor level of a dual occupancy development prior to the placement of concrete.	Mr Levick was cautioned	9 December 2010