

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Paul PEARCE BPB 0322	319	64 Provincial Road, Lindfield.	Mr Pearce failed to ensure that a condition of consent requiring certification of stormwater drainage works was satisfied prior to the issue of two occupation certificates.	Mr Pearce was reprimanded.	25 August 2011.