

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Lyall <b>DIX</b>	190	83 Chalmers Road STRATHFIELD	The certifier issued a construction certificate for a dwelling, swimming pool and outbuilding with the	No further action	3 Mar 2009
BPB No. 0092		STRATHFIELD	size of the outbuilding being inconsistent with the plans approved by the development consent		