

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Anthony <b>LEWIS</b>  BPB No. 0228	237	23 Emmett Street CALLALA BAY	<p>The certifier issued a final occupation certificate without ensuring that the development complied with the development consent including:</p> <ul style="list-style-type: none"> <li>▪ The finished floor level of the slab was constructed at a level lower than that approved by the development consent</li> <li>▪ The dwelling failed to comply with the Building Code of Australia</li> </ul>	Mr Lewis was reprimanded	13 Aug 2009