

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Scott <b>McGUFFICKE</b>  BPB No. 258	375	32 Gundaroo Circuit, Maryland	Mr McGufficke failed to ensure that a screen enclosure was provided with a satisfactory roof water drainage disposal system.	Mr McGufficke was reprimanded and fined \$2,000.	18 September 2014