

Summary of Disciplinary Action

Accredited	Disciplinary	Property	Details of disciplinary matter	Disciplinary action	Date of
certifier	action no.	address			decision
Vladan Blagojevic	433	25 Allwood Crescent, Lugarno	Prior to issuing a CDC, Mr Blagojevic failed to ensure the application included appropriate building plans viz., the plans	Mr Blagojevic was Reprimanded and required to	30 June 2016
BPB No. 2158			did not demonstrate how an external wall and openings would comply with the fire separation requirements of the BCA.	undertake the Building Regulation Short Course at UTS.	