

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Glenn FITZGIBBON BPB No. 0120	180	29 Maple Street ALBION PARK RAIL	Although a complying development certificate was issued for the construction of an above ground swimming pool, the certifier should not have issued an occupation certificate (for an above ground swimming pool) as the swimming pool, as constructed, was an in-ground fibreglass swimming pool	Mr Fitzgibbon was reprimanded	27 Jun 2008