

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Mark <b>SARGENT</b>  BPB No. 0361	192	17A Gardyne Street BRONTE	The certifier allowed works to occur on site that were inconsistent with the plans as approved by the development consent The certifier issued an interim occupation certificate in respect to a development that was inconsistent with the plans as approved by the construction certificate and the development consent	Mr Sargent was reprimanded and fined \$1000	31 Jul 2008