

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
<p>Lyll <b>Dix</b></p> <p>BPB No.092</p>	349	20-22 Clifton Street, Blacktown	<p>Mr Dix issued a final occupation certificate when the building had not been fitted with a fire hydrant system that complied with clause E1.3 (b) (i) of the BCA.</p> <p>Mr Dix issued a final occupation when the mechanical air handling system was not specified as an essential fire safety measure in the fire safety certificate that Mr Dix relied upon to issue the final occupation certificate.</p>	Mr Dix was reprimanded.	22 November 2012