

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Bernard COHEN BPB No. 0067	131	55 Rangers Road MOSMAN	 The certifier failed to endorse an application for a construction certificate with the date of its receipt The certifier issued a construction certificate on a date prior to having reportedly received the application The certifier issued a construction certificate contrary to council's development consent conditions requiring: The pool to be constructed wholly in the ground and the concourse to be a maximum of 500mm wide The pool to be constructed in accordance with the approved landscape plan A full schedule of finishes be provided to ensure that recessive non-reflective materials are used, particularly with regard to the roofing materials The submission of a 'Dilapidation Report of Street Assets' The certifier failed to ensure copies of the determination of the construction certificate together with copies of relevant plans and specifications were forwarded to council in accordance with the Regulation 	Mr Cohen was reprimanded and fined \$1000	8 Jun 2007