

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Paul <b>GEARIN</b>  BPB No. 0132	140	1A Wentworth Street POINT PIPER	The certifier issued a construction certificate without firstly ensuring Condition 38 of the development consent (information relating to and approval of a traffic signal system) had been satisfied	Mr Gearin was reprimanded	28 Sep 2007