

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Antonious GINDI BPB No. 0137	332	74 Waitara Parade Hurstville	Failure to take timely and appropriate action in relation to unauthorised building work and to ensure that the development was constructed in accordance with the development consent.	Mr Gindi was reprimanded and fined \$1000.	8 December 2011