

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Warrick <b>NORRIS</b>  BPB No. 0298	437	35 Edwards Road, Wahroonga	Issued a CDC for works that, in part, were not complying development under Codes SEPP or ARH SEPP, and allowed the secondary dwelling to have a set-back distance less than that permitted by ARH SEPP.	Mr Norris was Reprimanded and fined \$5000.	12 December 2016