

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Mr Paul Gearin BPB No.0132	259	3 Colgate Avenue, Balmain and 171 Darling Street, Balmain	Mr Gearin, principal certifying authority for the development, failed to adequately respond to written requests from Council to address matters relating to building works proceeding not in accordance with the development consents.	Mr Gearin was reprimanded and fined \$500.	3 December 2009