

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Peter <b>BURGESS</b> BPB No. 0052	264	1-3 Funda Place Brookvale	Issue of an occupation certificate for a residential flat building which was not suitable for occupation or use in accordance with its classification under the Building Code of Australia. The building was assessed for compliance with Type B fire safety requirements in lieu of a Type A as required by the Building Code of Australia. The building was non compliant with the Building Code of Australia requirements.	Mr Burgess was reprimanded and fined \$5000.00	3 December 2009