

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Camile HADDAD	369	123 Denison Street, Bondi Junction	Issuing an occupation certificate without ensuring that a party wall was constructed with the fire resistant level required by the Building Code of	Mr Haddad was cautioned and ordered to pay a fine	21 May 2014
BPB No. 0152			Australia.	of \$1500.	