

Summary of Disciplinary Action

Accredited	Disciplinary	Property address	Details of disciplinary matter	Disciplinary action	Date of
certifier	action no.				decision
Glenn	378	112 Janet Street,	Mr Levick while acting as the PCA failed to ensure	Mr Levick was	20/11/2014
LEVICK		Merewether	statutory requirements re builder's licence details,	reprimanded and	
			insurance, signage and notification were met.	ordered to pay a fine	
BPB No. 0027				of \$3,000.	