

Summary of Disciplinary Action

| Accredited certifier | Disciplinary action no. | Property address | Details of disciplinary matter | Disciplinary action | Date of decision |
|--|-------------------------|----------------------------------|---|--|------------------|
| Paul ARAMINI BPB No. 0013 | 379 | 133 Curlewis Street, Bondi Beach | Mr Aramini in the role of Principal Certifying Authority failed to take timely and appropriate action in regard to a complaint made to him about a ceiling installed that did not comply with a development consent condition concerning fire safety upgrading works to the building. | Mr Aramini was reprimanded and ordered to pay a fine of \$5,000. | 22/11/2014 |