

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
William DAGGER BPB No. 082	390	35-37 Coral Street The Entrance	Mr Dagger issued a complying development certificate (CDC) for development without a written report from another accredited certifier to confirm the proposed development was consistent with the existing building's alternative fire safety solution, and the fire safety schedule he attached to the CDC failed to include all existing fire safety measures and did not distinguish between existing and proposed fire safety measures.	Mr Dagger was reprimanded.	30 April 2015