

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Gordon DRYBURGH BPB No. 1186	439	1/26 Oakdale Road, Gateshead	Mr Dryburgh issued an interim occupation certificate (IOC) for a class 9b building without an access ramp for persons with a disability that was shown on the CDC plans.	Mr Dryburgh was Reprimanded	17 January 2017