



## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Raymond <b>JAMES</b>  BPB No.0193	98	241 St Marys Road Berkshire Park, 174 Linden Crescent Cranebrook, 1 Viola Place Glenmore Park, 104 Greys Lane Cranebrook, 284 Londonderry Road Londonderry, 112 Cherrybrook Chase Londonderry, 89 Greygums Road Cranebrook	Mr James was the applicant to a development application and was then appointed as the principal certifying authority for the developments. This practice constituted a potential conflict of interest.	Mr James was cautioned and conditions were imposed on his certificate of accreditation.	13 November 2006