

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Bernard COHEN BPB No. 0067	134	6-12 Nursery Street HORNSBY	<p>The certifier issued a construction certificate contrary to the conditions and plans approved by council's development namely:</p> <ul style="list-style-type: none"> ▪ windows were added along the western elevation of units 8, 9 and 12 in Block B, C and D, ▪ no survey reports were furnished to demonstrate the finished floor level of each level of construction, and ▪ an additional stair being located at the western side of the rear balcony to unit 8 	Mr Cohen was reprimanded and fined \$2000	8 Jun 2007